Stage 2 Planting



Stage 2 planting (infill between more established shrubs)



Stage 2 planting along edge of Pond 1





Bark mulch was spread generously to retain moisture during dry season

Maintenance



Removal of sediments near rock filter culvert between Ponds 1 and 2 with a long-reach digger is used only on an "as-required" basis



Recent photos – Feb 2019



All ponds now feature prolific growth of grasses, sedges etc



Trees are well established on the central island





Hives of bees ideally located on top of island, sheltered from wind by trees.

Bees obtain nectar from nearby manuka trees

